Appendix H Project Photographs (Existing and Proposed)

Photos of Existing Conditions

Photo 1. Rockwall Sidehill 1, view southeast (DSCN1872).

Photo 2. Rockwall Sidehill 2, view southeast (DSCN1873).

Photo 3. Johnson Pass Sidehill, view southwest (DSCN1875).

Photo 4. Johnson Pass Sidehill, view south (DSCN1877).

Photo 5. Johnson Pass Sidehill, view north (DSCN1878).

Photo 6. Midway Sidehill, view southeast (DSCN1879).

Photo 7. Midway Sidehill, view south (DSCN1880).

Photo 8. Meyers Grade Sidehill, north end, view south (DSCN1883).

Photo 9. Meyers Grade Sidehill, damage at south end, view southeast (DSCN1885).



Photo 10. Lauren's Lookout Sidehill, view southeast (DSCN1886).

Photo 11. Lauren's Lookout Sidehill, view south (DSCN1887).

Photo 12. Lauren's Lookout Sidehill, damage at midpoint, view northeast (DSCN1888).



Photo 13. Robbin's Run Sidehill, view south (DSCN1890).

Photo 14. Robbin's Run Sidehill, view southeast (DSCN1891).

Photo Simulation of Proposed Wall Barrier

Echo Summit - Photo simulation of the proposed wall barrier - viewing it from the highway.

Echo Summit - Photo simulation of the proposed wall barrier - viewing the outside of the wall.