# INFORMATION HANDOUT

**For Contract No. 02-4G2604**
**At 02-Plu-147-0.0/1.0**

**Identified by**
**Project ID 0213000087**

## MATERIALS INFORMATION

Pavement Coring Record

Water Source Information

# MATERIALS INFORMATION

Pavement Coring Record - Taken between PM 0.0 and 5.0 on Plumas 147

STATE C[illegible]ALIFORNIA
DEPART[illegible]NT OF TRANSPORTATION

# PAVEMENT CORE RECORD

0213000087

Contract # : 02-4G2600 Sheet 1 of 1

Cored By : Terry McCormick, Natalie R. Date 5-29-13

Federal # : Joel Gutsik

Job # :

Contract Limits : AC cores + R-value samples

Dist. 02 Co. Plu Rte 147 P.M. 0.0/2.5

| SOURCE | CHARGE | E.A. | SPECIAL D. # | ACTIVITY |
|---|---|---|---|---|
| 03 - 0365 | 02 - 0365 | 4G2601 | | 185 |

| CORE NO. | LOCATION | | | PAVEMENT THICKNESS | | BIT. DATA | | REMARKS |
|---|---|---|---|---|---|---|---|---|
| | STATION | LANE | POSITION | DESIGN | ACTUAL | CORE DIA. | SERIAL NO. | |
| | | | | AC | | 4" | | |
| 1 | PM 0.15 | N/B | 5FT. RT | 0.8' | | | | debonded at 0.6' |
| 2 | PM 0.5 | S/B | 5FT. RT | 0.6' | | | | |
| 3 | PM 1.0 | N/B | 5FT. RT | 0.6' | | | | |
| 4 | PM 1.5 | S/B | 5FT. RT | 0.62' | | | | |
| 5 | PM 2.0 | N/B | 5FT. RT | 0.62' | | | | |
| 6 | PM 2.4 | S/B | 5FT. RT | 0.65' | | | | debonding at 0.16' / stripping + delamination bottom 0.1' |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |

| Route | Direction | District | County | Lane |
|---|---|---|---|---|
| 147 | North | District 2 | Plumas | 1 |

Show cores independent of direction & lane

| | Start/End Range (mi) | | Inc |
|---|---|---|---|
| County ODM | 0.000 | 5.000 | 1.000 |
| Associated PM | 0.000 | 5.000 | |

- US Units-Ft
- US Units-In
- SI Units

Scaq Sdyhp hqwVwuxfwxuh

Eulgjhv2RK Frqqhfwruv Udp sv Odqhv Urxwh Erxqgdulhv P lvf



*11/10/2015*

**FOR CONTRACT NO.**: 02-4G2601
**PROJECT ID 02 1300 0087**

**ROUTE: 147 – PLU – PM 0.0/1.0**

# INFORMATION HANDOUT

# WATER SOURCE INFORMATION

Non-potable water sources have been identified for this project.

Identified non-potable water source

1) Indian Valley Community Services District
Source: Round Valley Reservoir

Contact

Jeff Titcomb, Office Manager, (530) 284-7224

http://www.indianvalleycsd.com/home.htm

Identified Potential water source

2) Hamilton Branch CSD

PH: (530) 596 – 3002

3) Private Water Source (Well)

Contact

Buzz McLaughlin (Owner), (530) 320 -2494